


(2)

2.

(1)

가

< >



(1)

1

$$= Z1/Z2 = n2/n1$$

Z1 =

Z2 =

n1 =



n2 =

1

> 1 ,

n1 <

n2 .



< 1 >

= n2
> n2
1
< 1 >

= 1 , n1
< 1 , n1

(Rack)

(L)

ISO

(KA)

(KA)

$$= \frac{Z_1}{360} \times m$$

m

2

$$= \frac{Z_1}{Z_2} \times \frac{Z_3}{Z_4} = \frac{n_2}{n_1} \times \frac{n_4}{n_3}$$

(n2 = n3)

2


< 2 >

2

2 3

(Idle)

$$= \frac{Z_1}{Z_2} \times \frac{Z_2}{Z_3} = \frac{Z_1}{Z_3}$$



< 2 > 2

< 1> ISO KA(ISO/DIS 6336/1)

()	1.00	1.25	1.75
가 (, 4)	1.25	1.50	2.00
(,)	1.50	1.75	2.25

(KA)

< 1>

< 1> 1.1

200%

가

= (KA) x

(Fly wheel)

가

(Sf)

AGMA


=

(Sf) x

(BT)

< 2> AGMA (AGMA 420.04)

,)	1/2	/日	0.50	0.80	1.25
	3	/日	0.80	1.00	1.50
	10	/日	1.00	1.25	1.75
	10	/日	1.25	1.50	2.00
()	1/2	/日	0.80	1.00	1.50
	3	/日	1.00	1.25	1.75
	10	/日	1.25	1.50	2.00
	10	/日	1.50	1.75	2.25
()	1/2	/日	1.00	1.25	1.75
	3	/日	1.25	1.50	2.00
	10	/日	1.50	1.75	2.25
	10	/日	1.75	2.00	2.50



$$= 0.7$$

$$= 0.8$$

$$= \frac{(Sf) \times (BT)}{BT = 2/3}$$

$$\times 1.5(3/2)$$

가

T_L ,

T_{L1}

$$t = \frac{[GD^2] (n_1 - n_0)}{375 (T_M - T_{L1})} \text{ (s)}$$

$$n_1 = \text{가} \quad (\text{rpm})$$

$$n_0 = \text{가}$$

$$n_0 = 0$$

$$t = \text{가} \quad ()$$

$$(GD^2) =$$

$$(GD^2) = (GD^2)_M + (GD^2)_{G1} + (GD^2)_{L1}$$

$$(GD^2)_M =$$

$$(GD^2)_{G1} =$$

$$(GD^2)_{L1} =$$

$$T_{STmax} = (T_M - T_{L1})$$

$$\times \frac{[GD^2]_{G1} + [GD^2]_{L1}}{[GD^2]_M + [GD^2]_{G1} + [GD^2]_{L1}} + T_{L1}$$

(3)

K_{lim}

406-01

T_M ,

(t)

K_{lim}

JGMA

$$d_1 = [(1.45) 10^6] \times \frac{1+u}{u \cdot k \cdot K_{lim}}]^{1/3} \cdot \left(\frac{P_A}{n_1}\right)^{1/3}$$

$$d_2 = [(1.45) 10^6] \times \frac{1+u}{u \cdot k \cdot K_{lim}}]^{1/3} \cdot \left(\frac{P_A}{n_2}\right)^{1/3}$$

$$d_1, d_2 = \quad (\text{mm})$$

$$u =$$

$$=$$

$$=$$

$$=$$

$$k =$$

$$= b/d_1 \quad (b =)$$

$$(n_1) \quad 3000\text{rpm}$$

$$k \quad 1.4$$

$$(n_1) \quad 3000\text{rpm}$$

$$, k \quad 2.0$$

$$(a) = 0.5 \times (d_1 + d_2)$$

$$(v) = \frac{d_1}{19.1} \times \frac{n}{1000} \text{ (m/s)}$$

$$(F_t) = \frac{75 \times P_A}{v}$$

[]
 4000kW, 1780rpm
 (7000rpm)

(K_A) = 1.25, k = 1.0, K_{lim} = 0.28 (kgf/mm²)

$$= \quad \times \quad = 1.25 \times 4000$$

$$= 5000 \text{ kW}$$

$$(u) = \frac{7200}{1780} = 4.04$$

$$d_2 = \left[(1.45 \times 10^6) \times \frac{1+4.04}{4.04 \times 1 \times 0.28} \right]^{1/3}$$

$$\cdot \left(\frac{5200}{7200} \right)^{1/3} = 167 \text{ (mm)}$$

$d_1 =$
 $d_2 =$

$$(v) = \frac{167}{19.1} \times \frac{7200}{10000} = 62.95 \text{ (m/s)}$$

$$(F_t) = \frac{75 \times 5000}{62.95} = 5957 \text{ (kgf)}$$

14 ~ 24
 가 14

$$Z_{\min} = Z_s + \frac{Z_s}{u}$$

$$Z_{\min} =$$

$$Z_s = \quad 30,$$

$$20$$

$$u = \quad (1 \quad)$$

$$Z_1 = Z_{\min} =$$

$$Z_2 = Z_1 \times u =$$


가 100 가
 가 가
 (change gear)가
 가
 가 가 가

$$(m) = d_1 / Z_1$$

() (b)

1
 2

, $b = 5_0 \sim 20_0$
 , $b = 20_0 \sim 35_0$



(Radial

Load) 가

(lead) p_z

$$d_1 = Z_1 \times m_t = \frac{Z_1 m_t}{\cos \alpha}$$

$$P_z = \frac{d_1}{\tan \alpha} = \frac{Z_1 m_n}{\tan \alpha}$$

$$= \tan^{-1} \left(\frac{d_1}{P_z} \right)$$

$$m_t =$$

$$m_n =$$

가 , 가
ercut)

20.
22.5°, 25°, 27°, 28°

가
(, und

가
14.5°, 17.5°, 18°, .

(W)

$$x = \left[\frac{W}{m} - \{Z \text{inv } \alpha + (Z_m - 0.5) \cos \alpha\} \right] \cdot \frac{1}{2 \sin \alpha}$$

$$W =$$

$$Z_m =$$

$$x_n = \left[\frac{W}{m_n} - \{Z \text{inv } \alpha_t + (Z_m - 0.5) \cos \alpha_n\} \right] \cdot \frac{1}{2 \sin \alpha_n}$$

$$m_n =$$

$$\alpha_t =$$

20. 가 17
가

가

$$x = \frac{17-Z}{17}$$

DIN

$$x = \frac{14-Z}{17}$$

$$(Z1) = 14,$$

$$(Z2) = 19$$

$$x_1 = \frac{17-13}{17} = 0.176$$

$$x_2 = \frac{17-19}{17} = -0.118$$

가 $x_2 = -0.118$ ()
 가 $x_2 = -0.176$.

$$s_a = m \left[\frac{1+2(1+x)}{Z} \right]$$

$$\left[\frac{1}{2} + 2x \tan \alpha + Z(\text{inv } \alpha - \text{inv } \alpha_a) \right]$$

$a =$

$$\text{inv } \alpha_w = 2 \tan \alpha \left(\frac{x_1 + x_2}{Z_1 + Z_2} \right) + \text{inv } \alpha$$

0.2m 0.4m

$$y = \frac{Z_1 + Z_2}{2} \left(\frac{\cos \alpha}{\cos \alpha_w} - 1 \right)$$

()

$$a = \left(\frac{Z_1 + Z_2}{2} + y \right) m$$

$\alpha_w =$
 $y =$ 가
 $a =$

$$(s_{1\min} + s_{2\min}) = -j_{t\min} + 2 a_{\min} \frac{\tan \alpha_n}{\cos \alpha_n}$$

$$(s_{1\min} + s_{2\max}) = j_{t\max} + 2 a_{\max} \frac{\tan \alpha_n}{\cos \alpha_n}$$

$$x_1 = (x_1 + x_2) \frac{Z_2}{Z_1 + Z_2}$$

$$j_{t\min} = +$$

$$j_{t\max} = +$$

$$a_{\min} =$$

$$a_{\max} =$$

$$s_{1\max} =$$

$$s_{2\max} =$$

$$s_{1\min} =$$



$$s_{2\min} =$$

$$x_2 = (x_1 + x_2) \frac{Z_1}{Z_1 + Z_2}$$



**

$$\cos \alpha_a = \frac{\cos \alpha}{1 + \frac{2(1+x)}{Z}}$$


VB)



< 3 >



< 4 >




0 =
< 4 >

(4)

< 3 >

< 5 >



$$F_1 = F_n \cos \alpha_n$$

$$F_r = F_n \sin \alpha_n$$

$$F_u = F_1 \cos \alpha_0$$

$$F_a = F_1 \sin \alpha_0$$

$$F_a = F_u \tan \alpha_0$$

$$F_r = F_u \frac{\tan \alpha_0}{\cos \alpha_0}$$

가 가

가

(,)

가

$\alpha_n =$

: (032)584-0430
<http://www.geartech.co.kr>